

Storage of filled PTFE gasket materials, expanded PTFE sheets, tapes and other products from PTFE

Recommended conditions:

- Dry and clean warehouse
- Storage temperature from -20°C to +40°C
- Relative humidity 50-60%
- Avoid direct sunlight
- Store in a horizontal position on a firm ground and in the original packaging
- Avoid mechanical damage during handling

Recommended storage time:

When those conditions are met, the storage period is 5 years.



Temac, a.s.
Zvěřínek 289 13
Czech Republic
Gasket and sealing technology

Telephone: +420 325 550 181
Fax: +420 325 550 250
e-mail: tech.help@temac.cz
www.temac.cz